

TOLSEN FORCE XPRESS

79005 CORDLESS SCREWDRIVER

INSTRUCTION MANUAL

4V



USCHOVEJTE TENTO NÁVOD!

Tuto příručku budete potřebovat pro bezpečnostní pokyny, provozní postupy a záruku.

Uložte jej a originální prodejní doklad na bezpečném suchém místě pro budoucí použití.

IMPORTANT SAFETY INFORMATION

спазвайте всички предупреждения за безопасност и всички инструкции. Неспазването на предупрежденията и инструкциите може да доведе до токов удар, пожар и/или опасност от токов удар.

Лична безопасност

- Бъдете нащрек, внимавайте какво правите и използвайте здрав разум, когато работите с електроинструмент, докато сте уморени или под въздействието на наркотици, алкохол или лекарства .
- Използвайте лични предпазни средства. Винаги носете предпазни средства за очи, като маска за прах, неплъзгащи се предпазни обувки, каска или защита за слуха, използвани при подходящи условия, ще намалят нараняванията.

Използване и грижа за акумулаторни инструменти

- Зареждайте само със зарядно устройство, посочено от производителя. Зарядно устройство, което е подходящо за един тип батерия, може да представлява опасност от пожар, когато се използва с друг тип батерия .
- Използвайте електрически инструменти само със специално предназначени батерии. Използването на други батерии крие риск от нараняване и пожар.

Servis

Nechte své elektrické nářadí opravit kvalifikovanou osobou, která bude používat pouze identické náhradní díly. Zajistíte tak zachování bezpečnosti elektrického nářadí.

Описание и спецификации

Въведение

Малка и компактна акумулаторна отвертка 4V. Затяга винтовете до максимална стойност 5 Nm и също така позволява допълнително затягане на винтовете с помощта ръчен въртящ момент до 10 Nm. Предлага се в кутия за съхранение с комплект от 20 бр битове за отвертка, включително магнитен държач за 1/4" удължителни битове. Вграденият светодиод осветява детайла, докато работите. Включва и LED индикатор състояние на зареждане на батерията.

Номинално напрежение 4VDC	
Мощност	1500mAh Li-ion батерия
Скорост на празен ход	n.; 250мин-'
Максимален въртящ момент	5 Nm
Зареждане	SV DC, макс.2.0 A
Чък	1/4" (6,35 мм)



Дистрибутор

Sunnysoft sro
Кованечка 2390/1a
190 00 Прага 9
Чехия
www.sunnysoft.cz

Списък с части




Обслужване

1. **ВАЖНА ГАРАНЦИОННА ИНФОРМАЦИЯ:** Батерията, инсталирана в тази безжична връзка батерия инструментът се счита за консуматив и способността му да приема такси.
2. За да заредите отвертката, поставете USB конектора в гнездото chargep на отвертката и включете другия край в подходящ източник на захранване.
3. Когато chargep, преен LED индикаторите мигат. Зеленият LED индикатор остава стабилен, когато е напълно зареден. LED индикаторът се изключва, когато батерията е изтощена.
4. Поставете накрайника в държача на отвертката. Използвайте превключвателя за напред/назад , за да изберете желаната посока и натиснете превключвателя за включване, за да стартирате отвертката. Работният светодиод светва при натискане на превключвателя и изгасва при отпускане на превключвателя.
5. За да промените посоката на въртене на отвертката, плъзнете контрола. към F или R, за да карате в обратната посока.
6. За да заключите шпиндела, плъзнете превключвателя за посоката на въртене в средно положение.
7. За да зададете използвания въртящ момент, използвайте бутона за избор на въртящ момент, когато отвертката не работи. Желаният въртящ момент може да бъде предварително избран в 3 степенувани стъпки. Всеки път, когато натиснете бутона за захранване, светодиодите ще светнат последователно (от най-малкия до най-големия). Колкото по-голям е светодиодът, толкова по-голям е въртящият момент.
8. Не претоварвайте електроинструмента, когато го използвате. Ако натоварването е Ако температурата на акумулатора е твърде висока или е превишена допустимата температура на акумулатора, електронното управление изключва електроинструмента, докато температурата се върне в оптималния температурен диапазон.

Поддръжка

1. Поддържайте отвертката чиста, като я избършете с влажна кърпа.
2. Съхранявайте отвертката и USB кабела на сухо място, недостъпно за

MONTÁŽNÍ SCHÉMA A SEZNAM DÍLŮ



Část	Popis	množství
1	Přední kryt	1
2	LED deska	1
3	Držák světelné desky	1
4	Pojistné kroužky	1
5	Distanční vložka	1
6	Položovací rozpěrka	1
7	Jaro	1
8	Sada převodovky	1
9	Paštorek	1
10	Konektor	1
11	Motor	1
12	komponenty PDB	1
13	Zadní kryt	1
14	Bydlení	1
15	Přepínací tlačítko	1
16	Funkční tlačítko	1

Доставчик/Дистрибутор

Sunnysoft sro
Кованечка 2390/1a
190 00 Прага 9

Чехия


www.sunnysoft.cz

TOLSEN **FX** FORCE XPRESS

79005 CORDLESS SCREWDRIVER

INSTRUCTION MANUAL

4V



SAVE THIS MANUAL !

You will need this manual for safety instructions, operating procedures and warranty.
Put it and the original sales receipt in a safe dry place for future reference.

IMPORTANT SAFETY INFORMATION



WARNING:

Read all safety warnings and all instructions. Failure to follow the warnings and instructions may result in electric shock, fire and/or serious injury.

Personal Safety

- Stay alert, watch what you are doing and use common sense when operating a power tool. Do not use a power tool while you are tired or under the influence of drugs, alcohol or medication. A moment of inattention while operating power tools may result in serious personal injury.
- Use personal protective equipment. Always wear eye protection. Protective equipment such as dust mask, nonskid safety shoes, hard hat, or hearing protection used for appropriate conditions will reduce personal injuries.

Battery Tool Use and Care

- Recharge only with the charger specified by the manufacturer. A charger that is suitable for one type of battery pack may create a risk of fire when used with another battery pack.
- Use power tools only with specifically designated battery packs. Use of any other battery packs may create a risk of injury and fire.

Service

Have your power tool serviced by a qualified repair person using only identical replacement parts. This will ensure that the safety of the power tool is maintained.

DESCRIPTION AND SPECIFICATIONS


Introduction

Small and compact rechargeable 4V screwdriver. Torques screws to a maximum of 5Nm and also allows screws to be further tightened with manual torque up to 10Nm. Supplied in a storage case with 20 screwdriver bit set including a magnetic 1/4" extension bit holder. Built in LED illuminates work piece upon operation. Also features LED battery level indicator.

Specifications

Rated voltage	4VDC
Power	1500mAh Li-ion battery
No-load speed	n_0 : 250min ⁻¹
Max. torque	5 N.m.
Charging	5V DC, Max.2.0A
Chuck	1/4" (6.35mm)



Component List


OPERATION

1. **IMPORTANT WARRANTY INFORMATION:** The battery fitted to this cordless tool is considered to be a consumable item and its ability to accept charge will reduce over time.
2. To charge the screwdriver, insert the USB connector into the charging socket on the screwdriver and plug the other end into a suitable power supply.
3. The green LED indicator lights are blinking while charging. The green LED indicator remains solid while fully charged. The LED indicator will go out when low battery.
4. Place a bit into the bit holder of the screwdriver. Select the required direction by using the forward/reverse switch and press the On switch to start the screwdriver. The LED worklight will light when the On switch is held down and will go off after the On switch is released.
5. To reverse the rotational direction of the screwdriver, slide the controller with towards the F or R to run in opposite direction.
6. To lock the spindle in place, slide the rotational direction switch into the middle position.
7. To set the torque applied, use the torque selection button while the screwdriver is not running. The required torque can be preselected in 3 graded steps. The LEDs will illuminate in turn (smaller to larger) for each press of the On button. The larger the illuminated LED, the greater the torque output.
8. When in use the power tool cannot be subject to overload. When the load is too high or the allowable battery temperature is exceeded, the electronic control switches off the power tool until the temperature is in the optimum temperature range again.

MAINTENANCE

1. Keep the screwdriver clean by wiping with a damp cloth.
2. Store screwdriver and USB cable in a dry, childproof area.

ASSEMBLY DIAGRAM & PARTS LIST



Part	Description	Qty.
1	Front cover	1
2	LED board	1
3	Light plate bracket	1
4	Circlips	1
5	Spacer	1
6	Positioning spacer	1
7	Spring	1
8	Gearbox set	1
9	Pinion	1
10	Connector	1
11	Motor	1
12	PDB components	1
13	Back cover	1
14	Housing	1
15	Switch button	1
16	Function push button	1

CE DECLARATION OF CONFORMITY

WE
SUZHOU TOLSEN TOOLS CO.,LTD.
198 HUASHAN ROAD, ZHANGJIAGANG,
JIANGSU, CHINA

Declare that the product
79005
CORDLESS SCREWDRIVER


Complies with the essential health and safety requirements of
the following Directices:
council directive 2006/42/EC

Standards and technical specifications referred to:
EN 55014-1:2017/A11:2020
EN IEC 61000-3-2:2019+A1:2020, EN
61000-3-3:2013+A1:2019
EN 55014-2:2015
EN 61000-4-2:2009, EN IEC 61000-4-3:2020, EN
61000-4-4:2012,
EN 61000-4-5:2014+A1:2017, EN 61000-4-6:2014/AC:2015,
EN IEC 61000-4-11:2020

Authorised Signatory and technical file holder

Signed for and on behalf of:
SUZHOU TOLSEN TOOLS CO.,LTD.
198 HUASHAN ROAD, ZHANGJIAGANG,
JIANGSU, CHINA
WANG QING
Group Quality Director
on: 14/11/2023





**SUZHOU TOLSEN
TOOLS CO.,LTD.**

www.tolsentools.com

TOLSEN is a trademark or
registered trademark of TOLSEN
TOOLS. All rights reserved.
MADE IN CHINA



SCAN TO VISIT
PRODUCT LINK